PATENT COSÉ

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of: Examiner: F. Alphonse RYOZO YANAGISAWA, et al. Group Art Unit: 2133 Appl. No.: 09/973,838 Filed: October 11, 2001 COORDINATE INPUT APPARATUS, For: COORDINATE INPUT METHOD, COORDINATE INPUT-OUTPUT APPARATUS, COORDINATE INPUT-OUTPUT UNIT, AND COORDINATE PLATE U.S. Patent No.: 6,965,377 B2 November 14, 2006 Issued: November 15, 2005

Commissioner for Patents Attn.: Certificate of Correction Branch P.O. Box 1450 Alexandria, VA 22313-1450

Certificate

NOV 2 0 2006

of Correction

CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee

for such Certificate of Correction.

Void date: 11/16/2006 SZEWDIE1 11/16/2006 SZEWDIE1 00000071 01 FC:1811

99973838 -100.00 OP

11/16/2006 SZEWDIE1 00000071 09973838

11/16/2006 SZEWDIE1 00000072 6965377

01 FC:1811

100.00 OP

Patentees' undersigned attorney may be reached in our Costa Mesa,
California office by telephone at (714) 540-8700. All correspondence should continue to
be directed to our address given below.

Respectfully submitted,

Edward A. Kmett Attorney for Patentees Registration No.: 42,746

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 Facsimile: (212) 218-2200

CA_MAIN 115903v1

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,965,377 B2

DATED

November 15, 2005

INVENTOR(S) :

RYOZO YANAGISAWA, et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 10:

Line 45, "regardless" should read --regardless of--.

COLUMN 12:

Line 47, "set adjust" should read --set--.

COLUMN 14:

Line 46, "32xi+1" should read --32Xi+1--.

COLUMN 16:

Line 19, "having" should read --has--. Line 20, "having" should read --has--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

PATENT NO. <u>6,965,377 B2</u>

No. of add'l. copies @ 30¢ per page

 \Box

NOV 2 0 2006

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,965,377 B2

DATED

November 15, 2005

INVENTOR(S) :

RYOZO YANAGISAWA, et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 10:

Line 45, "regardless" should read --regardless of--.

COLUMN 12:

Line 47, "set adjust" should read --set--.

COLUMN 14:

Line 46, "32xi+1" should read --32Xi+1--.

COLUMN 16:

Line 19, "having" should read --has--. Line 20, "having" should read --has--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

(Form#30)

PATENT NO. <u>6,965,377 B2</u>

No. of add'l. copies @ 30¢ per page

NOV 2 0 2006